

PANCHAYAT SAMITI HURDA DIST. BHILWARA (RAJ.)

916
20-9-24

BUILDING SAFETY CERTIFICATE

I do hereby certify that the Vivekananda Kendra Vidyalaya, Hurda school building is inspected by me and has been full fill sufficient parameters of building safety to my satisfaction. The condition of the building is fine.


सहायक अभियन्ता
JUNIOR ENGINEER
पंचायत समिति हर्दा (भीलवाड़ा)
PANCHAYAT SAMITI HURDA

CHECK-LIST FOR INSPECTION OF THE SCHOOL BUILDING

Name of the School : Vivekananda Kendra Vidyalaya, Hurda Dist. – Bhilwara (Raj.)

Date of Inspection : 17.9.24

916
20.9.24

Detail of item wise inspection for Building Safety

1. Building: -

I.	Walls	No any Leakage/Dampness
II.	Floors	No any Leakage/Dampness
III.	Roofs	No any Leakage/Dampness
IV.	Ceiling	No any Leakage/Dampness
V.	Parapet	No any Leakage/Dampness

2. Service: -

I.	Rain Water Pipe	No any Leakage
II.	Sewer Pipe	No any Leakage
III.	Water Pipe	No any Leakage

3. Whole the systems working Leak proof.

4. Septic tank, sock pit and outside drain are working properly satisfactorily.

5. Whole the building safety parameter fully full fill and building is good condition, maintenance properly.


JUNIOR ENGINEER
PANCHAYAT SAMITI HURDA