

PANCHAYAT SAMITI HURDA DIST. BHILWARA (RAJ.)

558
05-07-23

BUILDING SAFETY CERTIFICATE

I do hereby certify that the Vivekananda Kendra Vidyalaya, Hurda school building is inspected by me and has been full fill sufficient parameters of building safety to my satisfaction. The condition of the building is fine.


JUNIOR ENGINEER
PANCHAYAT SAMITI HURDA
सहायक अभियन्ता
पंच. स- हुरडा (भीलवाड़ा)

CHECK-LIST FOR INSPECTION OF THE SCHOOL BUILDING

Name of the School : Vivekananda Kendra Vidyalaya, Hurda Dist. – Bhilwara (Raj.)

Date of Inspection :

558
05-7-23

Detail of item wise inspection for Building Safety

1. Building: -

I. Walls	No any Leakage/Dampness
II. Floors	No any Leakage/Dampness
III. Roofs	No any Leakage/Dampness
IV. Ceiling	No any Leakage/Dampness
V. Parapet	No any Leakage/Dampness

2. Service: -

I. Rain Water Pipe	No any Leakage
II. Sewer Pipe	No any Leakage
III. Water Pipe	No any Leakage
IV. Fire Safety Equipment	Sufficient Quantity and Working Properly

3. Whole the systems working Leak proof.

4. Septic tank, sock pit and outside drain are working properly satisfactorily.

5. Whole the building safety parameter fully full fill and building is good condition, maintenance properly.

3
उपाध्यक्ष
JUNIOR ENGINEER
सहायक अभियंता
PANCHAYAT SAMITI HURDA
प. स. Hurda (भोलवाडी)